

**LEGEND**

- INDICATES DIRECTION OF FLOW
- EXISTING VEE GUTTER TO REMAIN
- - - - - EXISTING VEE GUTTER TO BE REMOVED
- NEW UNDERGROUND STORM DRAIN



**Teter Consultants**  
Structural Engineers and Architects

100 South Monroe • Visalia, California 93291 (559) 734-2100

**TULARE COUNTY RECYCLING COMPLEX  
DRAINAGE DIAGRAM**